

## SERVICES DIVISION INDICATIONS JOURNAL

24 January 1956

## Resurfacing of Lung-tien Airfield

The appearance of numerous construction sheds, piles of material and a new road in 24 December photography of the runway at Lung-t'ien airfield confirms field reports that it is being resurfaced. 1/ The original construction activity at this site failed to show the checker-board pattern which characterized the other jet fields under construction in 1955. The runway, which has been rated as serviceable for several months, was accordingly considered to be constructed of a different material — possibly asphaltic macadam. It may now be that unforeseen drainage problems at the low-lying Lung-t'ien site have made resurfacing necessary.

	25X1	
1	′	

S.F.C.D.F.M

NOTUDN